

Technical data: Z 110

	Z 110
Procedure	Plasma-cutting
Adjustable range cutting-current continuous	25-110 A
Cutting current at 100% duty cycle (40°C)	60 A
Duty cycle at max. current (40°C)	35 % (110 A)
Mains voltage	400 V
Power fuse slow	32 A tr.
Measurements approx. (LxWxH)	580x250x380 mm
Weight	31,5 Kg
Air consumption	200 l/min
Air pressure	5,5-7 bar
Max. cutting diameter (quality cut) steel	42 / 32 mm
Max. cutting diameter (quality cut) aluminium	27 / 22 mm
Max. cutting diameter (quality cut) stainless steel	30 / 24 mm

